



Figure 1: Upstream of culverts



Figure 2: Collapsed blue culvert



Figure 3: Settling pond failure



Figure 4: Settling pond failure, 2



Figure 5: Discharge from Property en route to Peaslee Creek



Figure 6: Discharge en route to Peaslee Creek, 2



Figure 7: Peaslee Creek



Figure 8: Peaslee Creek, 2



Figure 9: Peaslee Creek discharge to Tuolumne River



Figure 10: Tuolumne River upstream of Peaslee Creek discharge



Figure 11: Peaslee Creek upstream of Property discharge